

Pillow Ball Upper Mount

Each type Pillow Ball Upper Mount

Car		FRONT					REAR				
Model	Model Year	Type	PARTS No.	Pillow nut code	Pillow collar code	Remarks	Type	PARTS No.	Pillow nut code	Pillow collar code	Remarks

MITSUBISI

MIRAGE											
C53 ~ 83 CC, CA4A	87.9 ~ 91.9 91.10 ~ 95.9	Adjustable	511 410 A	H	01						
		Adjustable	508 410 A	H	01		Non adjustable	508 421 S		37 / 7	For STD type & ID70 springs.
							Non adjustable	508 421 A60		37 / 7	For ID60 springs.
CJ4A	95.10 ~						Non adjustable	508 421 A65		37 / 7	For ID65 springs.
		Adjustable	540 410 A	H	01		Non adjustable	508 421 S		37 / 7	For STD type & ID70 springs.
							Non adjustable	508 421 A60		37 / 7	For ID60 springs.
							Non adjustable	508 421 A65		37 / 7	For ID65 springs.

FTO

DE3A	94.10 ~	Adjustable	540 410 A	H	01		Non adjustable	508 421 S		37 / 7	For STD type & ID70 springs.
							Non adjustable	508 421 A60		37 / 7	For ID60 springs.
							Non adjustable	508 421 A65		37 / 7	For ID65 springs.

LANCER

A175A	81.10 ~ 87.10	Adjustable	506 410 A	H	01	Car hight goes up 10mm.					
		Non adjustable	506 411 A	H	01						
C63, 73	88.5 ~ 91.9	Adjustable	511 410 A	H	01						
CD5A, 9A CE9A	91.10 ~	Adjustable	508 410 A	H	01		Non adjustable	508 421 S		37 / 7	For STD type & ID70 springs.
							Non adjustable	508 421 A60		37 / 7	For ID60 springs.
							Non adjustable	508 421 A65		37 / 7	For ID65 springs.
CM5A		Adjustable	508 410 A	H	01		Non adjustable	508 421 S		37 / 7	For STD type & ID70 springs.
							Non adjustable	508 421 A60		37 / 7	For ID60 springs.
							Non adjustable	508 421 A65		37 / 7	For ID65 springs.
							Non adjustable	508 421 A		37 / 31	(Note 1)
CN9A, CP9A	96.10 ~ 01.1	Adjustable	540 410 A	H	01		Non adjustable	508 421 S		37 / 7	For STD type & ID70 springs.
							Non adjustable	508 421 A60		37 / 7	For ID60 springs.
							Non adjustable	508 421 A65		37 / 7	For ID65 springs.
							Non adjustable	508 421 A		37 / 31	(Note 1)
CT9A	01.1 ~	Adjustable	564 410 A	Q	01		Non adjustable	508 421 S		37 / 7	For STD type & ID70 springs.
							Non adjustable	508 421 A60		37 / 7	For ID60 springs.
							Non adjustable	508 421 A65		37 / 7	For ID65 springs.
							Non adjustable	508 421 A		37 / 31	(Note 1)

GTO

E-Z16A	90.10 ~	Adjustable	530 410 A	B	44		Non adjustable	530 421 A		65 / 66	
--------	---------	------------	-----------	---	----	--	----------------	-----------	--	---------	--

GALANT

A164A	80 ~ 83	Adjustable	522 410 A	H	01						
E38, 39	87.8 ~ 92.4	Adjustable	517 410 A	H	39		Non adjustable	517 421 A		40 / 41	For STD type springs.
E84	92.5 ~ 96.7										

DIAMANTE

F13 ~ 15	00.5 ~ 94.12	Adjustable	526 410 A	H	01		Non adjustable	517 421 A		40 / 41	For STD type springs.
----------	--------------	------------	-----------	---	----	--	----------------	-----------	--	---------	-----------------------

STARION

A183A, A187A	82.4 ~ 90	Adjustable	521 410 A	H	01						
--------------	-----------	------------	-----------	---	----	--	--	--	--	--	--

MINICA

H21 ~ 27	89.1 ~ 93.9	Non adjustable	500 411 A	J	36						
----------	-------------	----------------	-----------	---	----	--	--	--	--	--	--

PAJERO MINI

H56A	94.12 ~	Adjustable	820 410 A	I	58	For Turbo charger. Not for AT.					
------	---------	------------	-----------	---	----	--------------------------------	--	--	--	--	--

PAJERO Jr.

H57A	94.12 ~	Adjustable	820 410 A	I	58	For Turbo charger. Not for AT.					
------	---------	------------	-----------	---	----	--------------------------------	--	--	--	--	--

RVR

N23WG	92.10 ~	Adjustable	580 410 A	H	01						
-------	---------	------------	-----------	---	----	--	--	--	--	--	--

LEGNUM

EC5W	95.8 ~	Non adjustable	535 411 A	M	56	For STD type springs.	Non adjustable	535 421 A	M	51	For STD type springs.
		Non adjustable	535 411 A60	M	56	For ID60 springs.	Non adjustable	535 421 A60	M	51	For ID60 springs.
		Non adjustable	535 411 A70	M	56	For ID70 springs.	Non adjustable	535 421 A70	M	51	For ID70 springs.
		Non adjustable	535 411 A65	M	56	For ID65 springs.	Non adjustable	535 421 A65	M	51	For ID65 springs.

(Note 1) For straight type springs. Use with optional spring upper seats necessary.