

PILLOW BALL BUSHING

These pillow ball bushing need welding after press in.

Car	Model	Description	Necessary pieces	PARTS No.	Remarks
-----	-------	-------------	---------------------	-----------	---------

MAZDA

Roadstar	NA6C	F: LOWER ARM BUSHES	1set	404 464 BV	Front side. (Note 1)
		F: LOWER ARM BUSHES	1set	404 464 CV	Rear side. (Note 1)
		F: UPPER ARM BUSHES	2sets	404 464 KV	(Note 1)
		R: LOWER ARM BUSHES	2sets	404 464 HV	Out side.(Note 1)
		R: LOWER ARM BUSHES	2sets	404 464 IV	Body side(Note 1)
		R: UPPER ARM BUSHES	2sets	404 464 LV	Body side(Note 1)
		R: UPPER ARM BUSHES	1set	404 464 JV	Out side. (Note 1)
RX-7	SA22C	R: CONTROL ARM BUSHES	2sets	419 464 D	Upper side.
		R: CONTROL ARM BUSHES	2sets	419 464 E	Lower side.
	FC3S	R: TRAILING ARM BUSHES	1set	420 464 EV	(Note 1)

(Note 1) Including rubber boots.